



MGM Restoration

1232 Combermere
Troy, MI 48083

Insured: Metro Emergency Services
Property: 12535 Harper Avenue
Detroit, MI 48213

Business: (555) 555-5555

Claim Rep.: Marco Berard
Company: MGM Restoration
Business: 1232 Combermere
Troy, MI 48083

Business: (248) 356-4391

Estimator: Marco Berard
Company: MGM Restoration
Business: 1232 Combermere
Troy, MI 48083

Business: (248) 356-4391

Claim Number: CFP1004269-01A

Policy Number: CFP1004269-01A

Type of Loss: Vandalism

Coverage	Deductible	Policy Limit
SECURE	\$0.00	\$999,999.99

Date Contacted: 10/1/2009 11:00 AM
Date of Loss: 10/1/2009
Date Inspected: 10/6/2009 11:00 AM

Date Received: 10/1/2009 11:00 AM
Date Entered: 10/21/2009 1:40 PM

Price List: MIDE5B_DEC09
Restoration/Service/Remodel
Estimate: 12535_HARPER

NOTICE: This is a repair estimate only. The insurance policy may contain provisions that will reduce any payments that might be made. This is not an authorization to repair. Authorization to repair or guarantee of payment must come from the owner of the property. No adjuster or appraiser has the authority to authorize repair or guarantee payment. The insurer assumes no responsibility for the quality of repairs that might be made. A copy of this document does not constitute a settlement of this claim. The above figures are subject to insurance company approval.



MGM Restoration

1232 Combermere
Troy, MI 48083

12535_HARPER

Storage Area/Room

DESCRIPTION

HOURS	LBR. RATE	QUAN	UNIT	UNIT COST	MARKET COND.	TOTAL
LABOR	LBR. BURDEN	MATERIAL	EQUIPMENT	TOT. HARD		
Dumpster load - Approx. 40 yards, 7-8 tons of debris						
0.00	0.00	1.00	EA	598.50	0.00	598.50
				598.50	598.50	
Price charged by a waste management company to pickup and dump an extra large dumpster (approx 40 yds). Usually holds about 7-8 tons. As a general rule, the dumpster must be emptied every 5 to 7 days or additional fees may be charged.						
Dumpster load - retained per week						
0.00	0.00	23.00	WK	225.00	0.00	5,175.00
5175.00					5175.00	
Dumpster placed 10/15/2009.						
Administrative/supervisor labor charge						
0.00	0.00	1.00	EA	1,200.00	0.00	1,200.00
1200.00					1200.00	
Secure and monitor dumpster during period of ordered retention nad secure. Start Date 10/15/2009. On going.						
Totals: Storage Area/Room						
				6,973.50	0.00	6,973.50
6,375.00	0.00	0.00		598.50	6,973.50	
Line Item Totals: 12535_HARPER						
				6,973.50	0.00	6,973.50
6,375.00	0.00	0.00		598.50		

Grand Total Areas:

54,358.90	SF Walls	50,629.44	SF Ceiling	104,988.33	SF Walls and Ceiling
50,743.41	SF Floor	5,638.16	SY Flooring	6,844.14	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	6,763.06	LF Ceil. Perimeter
35,331.53	Floor Area	36,687.98	Total Area	52,955.20	Interior Wall Area
15,563.29	Exterior Wall Area	1,945.41	Exterior Perimeter of Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		



MGM Restoration

1232 Combermere
Troy, MI 48083

Summary for SECURE

Line Item Total	6,973.50
Replacement Cost Value	\$6,973.50
Net Claim	\$6,973.50

Marco Berard